

# **HISTORIC AMERICAN ENGINEERING RECORD**

## **INDEX TO PHOTOGRAPHS**

TUMALO IRRIGATION DISTRICT

HAER OR-151

West of Deschutes River

Tumalo vicinity

Deschutes County

Oregon

Pamela K. McKenney, Photographer (OR-151-1 through OR-151-52), March 2002.

Original captions for historic photographs provided in capital letters.

### **INDEX TO BLACK AND WHITE PHOTOGRAPHS**

OR-151-1	TYPICAL VIEW OF THE COLUMBIA SOUTHERN CANAL OPEN CHANNEL BETWEEN COLUMBIA SOUTHERN DIVISION STRUCTURE AND THE TUMALO FEED CANAL INTERSECTION. LOOKING NORTHEAST
OR-151-2	VIEW OF CONSTRUCTION CAMP ROCK FEATURE WITH OVER, ADJACENT TO THE COLUMBIA SOUTHERN CANAL. LOOKING NORTHWEST
OR-151-3	VIEW OF BEGINNING (UPSTREAM) OF THE COLUMBIA SOUTHERN CANAL'S "BIG CUT" BETWEEN CONSTRUCTION CAMP ROCK FEATURE AND THE COLUMBIA SOUTHERN DIVERSION STRUCTURE. LOOKING SOUTH/SOUTHEAST
OR-151-4	GENERAL VIEW (DOWNSTREAM) OF THE COLUMBIA SOUTHERN CANAL'S "BIG CUT." LOOKING NORTH/NORTHEAST
OR-151-5	GENERAL VIEW OF THE SETTLING-DIVERSION POND, THE TUMALO RESERVIOIR FEED CANAL INTAKE STRUCTURE, AND ADJACENT BRIDGE. LOOKING SOUTH

TUMALO IRRIGATION DISTRICT  
HAER OR-151  
INDEX TO PHOTOGRAPHS

OR-151-6	VIEW OF UPSTREAM SIDE OF TUMALO RESERVOIR FEED CANAL INTAKE STRUCTURE, OLD COLUMBIA SOUTHERN CANAL POND OUTLET (FAR LEFT), AND NEW COLUMBIA SOUTHERN CANAL INTAKE STRUCTURES (FAR RIGHT). LOOKING NORTH
OR-151-7	VIEW OF TWIN COLUMBIA SOUTHERN CANAL INTAKE STRUCTURES (POND SIDE), TUMALO RESERVOIR FEED CANAL INTAKE STRUCTURE TO LEFT. LOOKING NORTH/NORTHEAST
OR-151-8	TYPICAL VIEW OF LACEY LATERAL CANAL OPEN CHANNEL DOWNSTREAM OF POND. LOOKING EAST/NORTHEAST
OR-151-9	VIEW OF COLUMBIA SOUTHERN CANAL (UPSTREAM) AND THE WEST BRANCH COLUMBIA SOUTHERN CANAL DIVERSION STRUCTURE. LOOKING SOUTHWEST
OR-151-10	VIEW ACROSS COLUMBIA SOUTHERN CANAL AND THE WEST BRANCH COLUMBIA SOUTHERN CANAL DIVERSION STRUCTURE. LOOKING NORTH
OR-151-11	TYPICAL WOODEN TURNOUT OR DELIVERY ON WEST BRANCH COLUMBIA SOUTHERN CANAL. LOOKING WEST/SOUTHWEST
OR-151-12	TYPICAL VIEW OF WEST BRANCH COLUMBIA SOUTHERN CANAL OPEN CHANNEL BETWEEN WEST BRANCH DROP AND GERKING FLUME. LOOKING SOUTH/SOUTHEAST
OR-151-13	VIEW OF WEST BRANCH DROP (UPSTREAM), WEST BRANCH COLUMBIA SOUTHERN CANAL. LOOKING SOUTH
OR-151-14	VIEW OF GERKING FLUME INTAKE WITH TRASHRACK, WEST BRANCH COLUMBIA SOUTHERN CANAL. LOOKING NORTH/NORTHEAST
OR-151-15	VIEW OF GERKING FLUME (UPSTREAM) EAST SIDE GERKING MARKET ROAD. LOOKING SOUTHWEST

TUMALO IRRIGATION DISTRICT  
HAER OR-151  
INDEX TO PHOTOGRAPHS

OR-151-16	GENERAL VIEW GERKING FLUME OVER GERKING MARKET ROAD. LOOKING NORTH
OR-151-17	VIEW OF TUMALO DIVERSION DAM (RIGHT) AND TUMALO FEED CANAL INTAKE STRUCTURE (LEFT). FROM WEST BANK TUMALO CREEK. LOOKING NORTHEAST
OR-151-18	VIEW OF DOWNSTREAM SIDE OF TUMALO DIVERSION DAM AND SPILLWAY, WITH FISH LADDER TO RIGHT OF VIEW. FROM WEST BANK OF TUMALO CREEK. LOOKING SOUTHWEST
OR-151-19	VIEW OF CIPPOLETTI WEIR BELOW TUMALO DIVERSION DAM. FROM WEST BANK OF TUMALO CREEK. LOOKING SOUTHWEST
OR-151-20	VIEW OF DOWNSTREAM SIDE OF TUMALO FEED CANAL INTAKE STRUCTURE. LOOKING SOUTHWEST
OR-151-21	VIEW OF CONCRETE CHANNEL ADJACENT TO TUMALO FEED CANAL INTAKE STRUCTURE (DOWNSTREAM SIDE). LOOKING EAST/NORTHEAST
OR-151-22	VIEW OF TUMALO FEED CANAL INLET STRUCTURE TO PIPELINE BETWEEN THE CONCRETE CHANNEL AND UNLINED OPEN CHANNEL NEAR THE BEND FEED CANAL INTERSECTION. LOOKING NORTHEAST
OR-151-23	VIEW OF TUMALO FEED CANAL OUTLET STRUCTURE TO PIPELINE AT TRANSITION TO INLINED OPEN CHANNEL, UPSTREAM OF THE BEND FEED CANAL INTERSECTION. LOOKING SOUTH
OR-151-24	TYPICAL VIEW OF TUMALO FEED CANAL OPEN CHANNEL BETWEEN PIPELINE AND BEND FEED CANAL INTERSECTION. LOOKING NORTH/NORTHEAST
OR-151-25	TYPICAL VIEW OF TUMALO FEED CANAL OPEN CHANNEL WITH KLIPPEL SIPHON INLET STRUCTURE IN BACKGROUND. LOOKING SOUTHWEST

TUMALO IRRIGATION DISTRICT  
HAER OR-151  
INDEX TO PHOTOGRAPHS

OR-151-26	VIEW OF KLIPPEL SIPHON OUTLET STRUCTURE. LOOKING SOUTH
OR-151-27	TYPICAL VIEW OF TUMALO FEED CANAL OPEN CHANNEL UPSTREAM OF THE WEBER SIPHON. LOOKING NORTH
OR-151-28	VIEW OF CONCRETE FOOTINGS THAT ONCE SUPPORTED THE TWIN FLUMES AT ROCK CUT BELOW THE KLIPPEL FLUME (NOW KLIPPEL SIPHON). LOOKING WEST
OR-151-29	VIEW OF MORTARED ROCK FOOTING THAT ONCE SUPPORTED THE TWIN FLUME'S OUTLET TO TUMALO FEED CANAL, WITH BRIDGE. LOOKING NORTHWEST
OR-151-30	GENERAL VIEW OF BRIDGE CROSSING OF TUMALO FEED CANAL, TWIN FLUME'S OUTLET ROCK FOOTING ON RIGHT CANAL BANK. LOOKING WEST
OR-151-31	VIEW OF CONCRETE DELIVERY TO PAULY LATERAL CANAL. LOOKING WEST
OR-151-32	GENERAL VIEW OF CHECK DAM (UPSTREAM SIDE), CONCRETE LINED TUMALO RESERVOIR FEED CANAL, AND UPPER TUMALO RESERVOIR (IN BACKGROUND) NEAR COLLINS ROAD. LOOKING WEST
OR-151-33	VIEW OF DOWNSTREAM SIDE OF CHECK DAM, CONCRETE SPILLWAY WITH MORTARED ROCK WALLS, AND CIPPOLETTI WEIR ON TUMALO RESERVOIR FEED CANAL NEAR COLLINS ROAD (IN BACKGROUND). LOOKING NORTHEAST
OR-151-34	VIEW OF MORTARED ROCK AND CONCRETE INLET TO COUCH LATERAL CANAL, UPSTREAM OF COLLINS ROAD. LOOKING NORTH/NORTHEAST
OR-151-35	GENERAL VIEW OF A PORTION OF TUMALO RESERVOIR FROM OUTSIDE THE UPPER TUMALO RESERVOIR DIKE. LOOKING SOUTH/SOUTHEAST

TUMALO IRRIGATION DISTRICT  
HAER OR-151  
INDEX TO PHOTOGRAPHS

OR-151-36	VIEW OF WIMER CANAL (CENTER MIDDLE GROUND) NEAR CROSSING OF SISEMORE ROAD. LOOKING NORTHWEST
OR-151-37	VIEW OF SEGMENT OF DIKE CREATING UPPER TUMALO RESERVOIR FROM TUMALO RESERVOIR. LOOKING EAST/SOUTHEAST
OR-151-38	GENERAL VIEW OF UPPER TUMALO RESERVOIR FROM OUTLET OF TUMALO RESERVOIR FEED CANAL. LOOKING WEST/SOUTHWEST
OR-151-39	VIEW OF BLAKELY ROAD ACROSS TUMALO DAM, RESERVOIR SIDE TO RIGHT AND DOWNSTREAM SIDE TO LEFT. LOOKING EAST
OR-151-40	VIEW OF BLAKELY ROAD ACROSS TUMALO DAM, DOWNSTREAM SIDE TO LEFT AND RESERVOIR SIDE TO RIGHT. LOOKING WEST
OR-151-41	GENERAL VIEW OF RESERVOIR SIDE OF TUMALO DAM FROM TUMALO RESERVOIR FLOOR, WITH CONTROL HOUSE TO LEFT. LOOKING NORTH
OR-151-42	VIEW OF HAND-LAID RIPRAP ON RESERVOIR SIDE OF TUMALO DAM. LOOKING NORTH
OR-151-43	GENERAL VIEW OF RESERVOIR SIDE OT TUMALO DAM AND CONTROL HOUSE. LOOKING WEST
OR-151-44	VIEW OF TUMALO DAM CONTROL HOUSE. LOOKING NORTHWEST
OR-151-45	GENERAL VIEW RESERVOIR SIDE OF BULL CREEK DAM AND BRIDGE. LOOKING NORTHWEST
OR-151-46	VIEW OF BULL CREEK DAM AND BRIDGE, WITH TRASHRACK ON RESERVOIR SIDE. LOOKING SOUTHEAST

TUMALO IRRIGATION DISTRICT  
HAER OR-151  
INDEX TO PHOTOGRAPHS

OR-151-47	GENERAL VIEW OF DRY-LAID ROCK CUTOFF WALLS ALONG NORTH EDGE OF TUMALO RESERVOIR AND ADJACENT TO NORTH SIDE OF BULL CREEK DAM AND BRIDGE. LOOKING NORTHWEST
OR-151-48	VIEW OF DOWNSTREAM SIDE OF BULL CREEK DAM AND BRIDGE, WITH LATER HEADGATE ADDITION THROUGH SPILLWAY. LOOKING WEST
OR-151-49	VIEW OF HIGHLINE DROP ON THE HIGHLINE LATERAL CANAL DOWNSTREAM FROM BULLCREEK DAM AND BRIDGE. LOOKING SOUTHEAST
OR-151-50	GENERAL VIEW OF TUMALO FEED CANAL (RIGHT) AND BEND FEED CANAL (LEFT) INTERSECTION. LOOKING SOUTHEAST
OR-151-51	VIEW OF BEND FEED CANAL FLUME #4 REPLACEMENT SIPHON OUTLET STRUCTURE ON WEST BANK OF TUMALO CREEK. LOOKING EAST
OR-151-52	GENERAL VIEW ROUTE OF BEND FEED CANAL FLUME #4 REPLACEMENT SIPHON FROM WEST BANK TUMALO CREEK. LOOKING EAST
OR-151-53	Photographic copy of TID photograph (from original print on file at TID office, Tumalo, Oregon). Photographer unknown, ca. 1913 -1914 (Tumalo Project canal construction with horses, fresno scrapers, and observers)
OR-151-54	Photographic copy of TID photograph (from original print on file at TID office, Tumalo, Oregon). Photographer unknown, ca. 1913 -1914 (Tumalo Project canal construction with large crew of men, horses, and mules)
OR-151-55	Photographic copy of TID photograph (from original print on file at TID office, Tumalo, Oregon). Photographer unknown, ca. 1914 (MAIN CANAL FINISHING CREW AT WORK - CAMP #7)

TUMALO IRRIGATION DISTRICT  
HAER OR-151  
INDEX TO PHOTOGRAPHS

OR-151-56	Photographic copy of TID photograph (from original print on file at TID office, Tumalo, Oregon). Photographer unknown, ca. 1913 -1914 (Tumalo Dam construction, looking over dam to Tumalo Reservoir)
OR-151-57	Photographic copy of TID photograph (from original print on file at TID office, Tumalo, Oregon). Photographer unknown, ca. 1914 (TUMALO DAM - LAYING RIPRAP)
OR-151-58	Photographic copy of TID photograph (from original print on file at TID office, Tumalo, Oregon). Photographer unknown, ca. 1913 -1914 (BULL CREEK DAM. CONSTRUCTION OF WEIR & PIERS)
OR-151-59	Photographic copy of TID photograph (from original print on file at TID office, Tumalo, Oregon). Photographer unknown, ca. 1913 -1914 (BULL CREEK DAM. SPILLWAY AND BRIDGE)